

## **UPStealth 2 Firmware and Software Release Notes**

Version v1.2.13

Release Date: March 18, 2022

### **UPStealth 2 UPS 1000W/1500W**

#### **Enhancements**

1. Complete network configuration is now displayed on the LCD Network screen.
2. Network Configurations can now be changed from the LCD screen by using the Navigation dial to select Network, then select Network Configuration.
3. Increase web application performance through web server performance improvements.
4. The Serial number of the UPStealth 2 UPS 1000W/1500W is now displayed on the LCD Screen.
5. Revision changed to 1.2.13

### **UPStealth 2 Battery 500W**

1. Revision changed to 1.2.13

### **UPStealth 2 XRT Battery 3600W IMS**

#### **Bug Fix**

1. Ensure that when XRT is in an error state that the battery bus will not be turned on.
2. Revision changed to 1.2.13

### **UPStealth 2 Software**

#### **Enhancements**

1. Increase performance through better caching of web artifacts.
2. Simplify time selection dialog.
3. Revision changed to 1.2.13

### **UPS Firmware V1.2.12 Release Notes (Note: limited release)**

#### **UPStealth 2 UPS 1000W/1500W**

##### **Enhancements**

1. Increase web application performance through web server performance improvements.
2. Revision changed to 1.2.12

#### **UPS Battery 500W**

1. Revision changed to 1.2.12

#### **UPStealth 2 XRT Battery 3600W IMS**

1. Revision changed to 1.2.12

## **UPStealth 2 Software Enhancements**

1. Increase performance through better caching of web artifacts.
2. Simplify time selection dialog.
3. Revision changed to 1.2.12

## **UPS Firmware V1.2.11 Release Notes (Note: limited release)**

### **UPStealth 2 UPS 1000W/1500W**

#### **Bug Fix**

1. Turned on TCP\_LISTEN\_BACKLOG to prevent unnecessary TCP resets.
2. Closed network socket before resetting due to firmware update or network config change.
3. Trigger was firing prematurely for the Power-Fail + Delay.
4. Revision changed to 1.2.11

### **UPStealth 2 Battery 500W**

1. Revision changed to 1.2.11

### **UPStealth 2 XRT Battery 3600W IMS**

1. Revision changed to 1.2.11

### **UPStealth 2 Software**

1. Revision changed to 1.2.11